

Hartland®

Top-mount Kitchen Sink

K-5818-1

Features

- 36-inch minimum base cabinet width.
- Double equal bowls.
- 9-inch depth.
- Single faucet hole.
- Rear drain increases workspace in the sink and storage space underneath.

Material

KOHLER® enameled cast iron.

Installation

Top-mount

Recommended Products/Accessories

K-9000 P-Trap

K-6539 Drainboard with Sink Rack

K-6377 Sponge Caddy

K-6378 Kitchen Brush Caddy

K-6379 Kitchen Squeegee

K-6382 Disinfecting Wipes Dispenser

K-6383 Soap Dispenser

K-8618 Paper Towel Holder

K-8619 Flexible Kitchen Mat

K-8624 Dish Scraper

K-5133 Left-Bowl Sink Rack

K-5135 Right-Bowl Sink Rack

K-8801 Sink Strainer

K-8799 Sink Strainer

Optional Products/Accessories

K-6016L Left-Bowl Sink Rack

K-6016R Right-Bowl Sink Rack

K-6545 Sponge Caddy

K-6603L Sink Basket

K-6603R Sink Basket

Included Components

Product consists of:

1054375 Under-mount Sink Kit, 23"



Codes/Standards

ASME A112.19.1/CSA B45.2

KOHLER® Enameled Cast Iron Kitchen Sink Lifetime Limited Warranty

See website for detailed warranty information.

Available Colors/Finishes

Color tiles intended for reference only.


Color	Code	Description
	0	White
	FF	Sea Salt™
	96	Biscuit
	47	Almond
	FD	Cane Sugar™
	95	Ice™ Grey
	K4	Cashmere
4	7	Black Black™







Top-mount Kitchen Sink K-5818-1



Technical Information

All product dimensions are nominal.

Bowl configuration: Double equal
Installation: Top-mount
Min. base cabinet 33" (838 mm)

width:

Bowl area (Left): Length: 14-1/8" (359 mm)

Width: 16-1/4" (413 mm) Bowl depth: 9" (229 mm)

Bowl area (Right): Length: 14-1/8" (359 mm)

Width: 16-1/4" (413 mm) Bowl depth: 9" (229 mm)

Number of deck holes: 1

Faucet hole(s): 1-3/8" (35 mm)
Drain hole: 3-7/8" (98 mm)

Template: 1125670-7, required, included

Notes

Install this product according to the installation instructions.

NOTICE: The countertop manufacturer or cutter must use the cut-out template provided with the product, or a current one provided by the Kohler Co. (Call 1-800-4-KOHLER.) Kohler Co. is not responsible for cut-out errors when the incorrect cut-out template is used.

